IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System — G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR J. P. Van Hoy DATE May 5, 1977 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION I-77N, T.L. on 901, T.L. on R851 [redacted] (1st gravel Rd), go to Stop sign and T.L. on 1852, go to 1st dirt Rd on Rt (1854) T.R., go to end mobile home on right S. R. No. _____


SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms 1

Garbage Disposal Unit	Yes ( )	No ( )	Character & Porosity of Soil	Cecil Clay
Auto. Dishwasher	Yes ( )	No ( )	Percolation Rate	none
Auto. Wash. Machine	Yes ( )	No ( )	Topography	2-6% slope to left
Site Suitable	Yes ( )	No ( )	Depth to Water Table	unk
			Rock or other impervious formations	none observed

Lot Area acreage



Plot of System

Size of Tank [redacted] 250 Gals.

Nitrification Field:
No. of Lines 2
Sq. Ft. 625 Linear Ft. 250
Depth of Stone in Lines 10"

Water Supply: Individual (✓)
Public ( )

Installed by Hal Dobson

IMPROVEMENTS PERMIT BY _____

COMMENTS: Siften particals covered before inspection, contractor agreed to uncover portions for inspection, 3 visits made for inspection, well not installed during inspections

CERTIFICATE OF COMPLETION BY Arden E. Carey & Kellie W. Johnson R.S. DATE May 5, 1977

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold