IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Tommy Smith DATE 25 Mar 75 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION I 77 N. to 901 - T.L. to 1st pond Rt to Cliff. to 1851 - to T to Rt sign - T. Cliff. 2 mi. last house on Left S. R. No. _____

SUBDIVISION NAME Shaw Mill Rd LOT NO. _____ SECTION OR BLOCK NO. _____


House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 1½

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes ( )	No (✓)	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Character & Porosity of Soil Cecil Cly Loam
Percolation Rate 60MPI
Topography Slope to rear of house
Depth to Water Table 60"
Rock or other impervious formations None

Lot Area acreage



Plot of System Shaw Mill Rd

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 1
Sq. Ft. 390 Linear Ft. 130
Depth of Stone in Lines 10" plus
Water Supply: Individual (✓)
Public ( )

Installed by Ray Lentz

IMPROVEMENTS PERMIT BY _____

COMMENTS: Too much fall on all line - new line laid with all line approx 1" lower. Very good soil - Tank shall be pumped with last year as well.

CERTIFICATE OF COMPLETION BY Jesse Howard DATE 25 Mar 21

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold