DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet 1 of 1
PROPERTY ID #: 485273498
COUNTY: IREDELL

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: MILDRED DEATON APPLICANT: IMOGENE RENEGAR
ADDRESS: 701 JERICHO RD, HARMONY APPLICATION DATE: 2-8-99 DATE EVALUATED: 3-1-99
PROPOSED FACILITY: 2BR S/W MH PROPOSED DESIGN FLOW (.1949): 240 PROPERTY SIZE: 1.51 ACRES
LOCATION OF SITE: 701 JERICHO ROAD, HARMONY PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☑ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 1%	0-48	SBK / C-CL	FR FI / SERP					PS 0.3
2	L 1%	0-48	SBK / C-CL	FR-FI / SERP					PS 0.3
3	L 1%	0-48	SBK / C-CL	FR-FI / SERP					PS 0.3
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	S	S
System Type(s)	I	I
Site LTAR	0.3	0.3

OTHER FACTORS (.1946): NONE
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: S. HEDRICK
OTHER(S) PRESENT: J.C. AUTRY, IMOGENE RENEGAR