DEPARTMENT OF ENVIRONMENTAL HEALTH
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #:
COUNTY: Franklin

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Tileatha Lynn APPLICANT:
ADDRESS: APPLICATION DATE: DATE EVALUATED: 10-18-16
PROPOSED FACILITY: PROPOSED DESIGN FLOW (.1949): 360gpd PROPERTY SIZE:
LOCATION OF SITE: 1113 Union Grove Rd PROPERTY RECORDED:
WATER SUPPLY: ☐ Private ☒ Public ☐ Well ☐ Spring ☐ Other
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) 1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	4%	0-12"	Brw SCL	GR, FR					PS .25-.3
		12-36	Rd C/CLm-w	SBK SS, SP, SExp, FR					
		36-46	Rd CL w	SBK SS, SP, SExp, FR					
			w/ Few to many	Quartz Incl		Incl Thru Auger			
		46	Rock	Coulder?					
2	L 5%	0-10"	Brw SCL	GR, FR					PS .3
		10"-48	Rd/C/CLm-w	SBK SS, SP, SExp, FR		Rock			
			w/ Few to many	Quartz					
			Incl	@ 45"-48"					
3	4%	0-3	Brw SCL	GR, FR					PS .3
		3-45	Rd C/CLm-w	SBK SS, SP, SExp, FR		Rock Incl			
			w/ Few	Quartz					
		46"	Rock						
4	5%	0-6"	Brw SCL	GR, FR					PS .3
		6-48"	R/C/CLm-w	SBK SS, SP, SExp, FR		>42"			
			SAP w/ Rock	Incl					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	25% Red	50% Red
Site LTAR	.3	

OTHER FACTORS (.1946):
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: Maria Dotson
OTHER(S) PRESENT: