IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Shumaker & McCann Builders DATE June 15, '78 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION I-77 N T.L. on 901 T.R. in Union Grove onto SR 1832 (Zion Ch. Rd.) Go ~ 2½ mi x creek on left S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____


House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes ( )	No (✓)	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Character & Porosity of Soil Cecil clay loam
Percolation Rate _____
Topography 4-6%
Depth to Water Table sat.
Rock or other impervious formations none obs.

Lot Area acreage



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 2
Sq. Ft. 600 Linear Ft. 200
Depth of Stone in Lines 10" +
Water Supply: Individual (✓)
Public ( )

Installed by Hoke Bros

IMPROVEMENTS PERMIT BY H. R. Hinson

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Harold R. Hinson DATE June 15, '78

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold