IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Shumaker & McCann Builders DATE June 15, '78 PERMIT NO. _____

PHONE: Business _____ Home _____


LOCATION I-77 N T.L. on 901 T.R. in Union Grove onto SR 1832 (Zion Ch. Rd.) Go ~ 2½ mi x creek on left S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2
Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes ( ) No (✓)
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )
Lot Area acreage

Character & Porosity of Soil Cecil clay loam
Percolation Rate _____
Topography Hilly
Depth to Water Table deep.
Rock or other impervious formations none obs.



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 2
Sq. Ft. 600 Linear Ft. 200
Depth of Stone in Lines 10"+
Water Supply: Individual (✓)
Public ( )

Installed by Hoke Bros

The location of the proposed DEN ADDITION addition does not appear to impact the existing septic system.
**NOTE: _____
R. STEVE HEDRICK REHS
Date: NOVEMBER 15, 2010
ICHD-Environmental Health Division

IMPROVEMENTS PERMIT BY H.R. Henson

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Harold R. Henson DATE June 15, '78

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold