DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of _
PROPERTY ID #:
COUNTY: REDEY

4853-61-3675 (PT)

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: RALPH DILLOW APPLICANT: SAME
ADDRESS: 9024 DETROITER DR HUNTSVILLE APPLICATION DATE: 2-15-00 DATE EVALUATED: 2-29-00
PROPOSED FACILITY: 3 BR S/W MH PROPOSED DESIGN FLOW (.1949): 360 PROPERTY SIZE: 11.22 AC
LOCATION OF SITE: FOXFIELD LANE, AT END BEHIND HOUSE PROPERTY RECORDED: ___
WATER SUPPLY: ☑ Private ☐ Public ☐ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFIL. CLASS & LTAR
1	L 15%	0-21	SBK / C	FI/S-P/NEXP		44			PI
		21+	ROCK						
2	L 8%	0-20	SBK / C	FI/S-P/NEXP			PS		PS 0.25
		20-40	SBK / SiC	FR/SS-SP/NEXP					
		40-48	SAPROLITE						
3	L 8%	0-22	SBK / C	FI/S P/NEXP			PS		PS 0.25
		22-40	SBK / SiC	FR/SS-SP/NEXP					
		40-48	SAPROLITE						
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	S	S
System Type(s)	II	II
Site LTAR	0.25	0.25

OTHER FACTORS (.1946): NONE
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: S. HEDRICK
OTHER(S) PRESENT: TINA DILLOW