IREDELL COUNTY HEALTH DEPARTMENT

IMPROVEMENT PERMIT AND CERTIFICATE OF COMPLETION / OPERATIONS PERMIT

16192

OWNER OR CONTRACTOR BARBARA T. BENGE DATE 4/15/93 PERMIT NO. 16P-A-65

PHONE: Business _____ Home _____

LOCATION I-77 N, TL NC 901 W, TR UNION GROVE ROAD, TL TUTTEROW ROAD, ~ 0.4 MILE ON (R) S.R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House ☑ Mobile Home ☐ Business ☐ Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ☐ No ☑

Auto. Dishwasher Yes ☑ No ☐

Auto. Wash. Machine Yes ☑ No ☐

Lot Area 1.5 AC

Soil Characteristics _____


Application Rate _____

Topography _____

Depth to Water Table _____

Rock or other impervious formations EXISTING

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement _____ Crawl Space



Plot of System (Not to Scale)

Size of Tank _____ Gals.

Nitrification Field:

No. of Lines EXISTING

Sq. Ft. _____ Linear Ft. _____

Depth of Stone in Lines _____

Water Supply: Individual ☑ WELL

Public ☐

Installed by _____

I understand and agree to install a septic tank system as specified on this Improvement Permit.

Signed: _____

(IMPROVEMENT PERMIT IS VALID FOR 60 MONTHS FROM DATE OF ISSUE.)

IMPROVEMENT PERMIT BY _____

COMMENTS (1) KEEP HOUSE MINIMUM 5' FROM ~~HOUSE~~ SEPTIC SYSTEM.
(2) NO VEHICULAR TRAFFIC PERMITTED OVER SEPTIC SYSTEM

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY STEVE HEDRICK DATE 4/15/93

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS

Permit is VOID if any unauthorized changes are made in installation of system, and/or if any unapproved changes are made to the site, and/or if any false information is supplied toward securing Improvement Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold