DEPARTMENT OF ENVIRONMENT,
HEALTH & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

DRAFT

SHEET 1 OF 1
PROPERTY I.D.#: 16P-A-92
DATE: 8-25-95
COUNTY: IREDELL

SOIL SITE EVALUATION FOR ON-SITE WASTEWATER SYSTEM

APPLICANT: DEBRA B. GREEN / LYNNE HAWBY OWNER ✓ AGENT: PHONE: 539-5396
ADDRESS: 118 FARMLAND DRIVE
UNION GROVE, NC 28689
APPLICATION DATE: 8-17-95 DATE EVALUATED 8-25-95
PROPOSED FACILITY: 3BR D/W MH
PROPERTY SIZE: 10 ACRES
LOCATION OF SITE: I-77 N, EXIT NC901, TR UNION GROVE ROAD, TR HOLLAND FARM RD, 1ST MH on R PAST FARMLAND DR
WATER SUPPLY: On-site Well ✓ Comm. Well ___ Public ___ Other ___ EVAL. METHOD: Auger Boring ✓ Pit ___ Cut ___

PROFILE #	.1940 LANDSCP POS./ SLOPE(%)	HORIZON DEPTH (IN.)	.1941 (a)(1) TEXTURE	.1941 a)(2) STRUCTURE	.1941 (a)(3) MINEROLOGY	MATRIX COLOR	MOTTLE COLOR	OTHER PROFILE FACTORS	
1	L	0-36	GR/C	SBK	1:1 / FI			.1942 Wetness Cond.	-5
	2%	36-48	GR/SC	WSBK	1:1 / FI			.1943 Depth/.1956 Sapr.	-5
								.1944 Restrictive Hori.	-5
								.1948 Profile Class.	PS
								Profile LTAR	0.3
2	L	0-36	GR/C	SBK	1:1 / FI			.1942 Wetness Cond.	-5
	2%	36-48	GR/SC	WSBK	1:1 / FI			.1943 Depth/.1956 Sapr.	-5
								.1944 Restrictive Hori.	-5
								.1948 Profile Class.	PS
								Profile LTAR	0.3
3								.1942 Wetness Cond.	-
								.1943 Depth/.1956 Sapr.	-
								.1944 Restrictive Hori.	-
								.1948 Profile Class.	-
								Profile LTAR	-
4								.1942 Wetness Cond.	-
								.1943 Depth/.1956 Sapr.	-
								.1944 Restrictive Hori.	-
								.1948 Profile Class.	-
								Profile LTAR	-

AVAILABLE SPACE (.1945) 5 OTHER FACTORS (.1946) NONE SITECLASSIFICATION (.1948) PS
SYSTEM TYPE CONV. GRAVITY LONG-TERM ACCEPTANCE RATE(S) 0.3 GPD/FT²
EVALUATED BY: STEVE HEDRICK OTHER(S) PRESENT: DEBRA GREEN
COMMENTS:

0004006