# IREDELL COUNTY HEALTH DEPARTMENT

## (SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System — G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Jack Messick DATE 9 June 76 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION Hwy 21 N to Tabor Ch. Rd. # 1945 - Go 2.3 miles - House on Left. S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____


House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 1

| | | |
|---|---|---|
| Garbage Disposal Unit | Yes ( ) | No (✓) |
| Auto. Dishwasher | Yes ( ) | No (✓) |
| Auto. Wash. Machine | Yes (✓) | No ( ) |
| Site Suitable | Yes (✓) | No ( ) |

Character & Porosity of Soil Coal clay
Percolation Rate none
Topography 2-6 Go Hope
Depth to Water Table unk
Rock or other impervious formations unk

Lot Area average




Plot of System Tabor Church Rd.

Size of Tank 1250 ? Gals.
Nitrification Field:
No. of Lines _____
Sq. Ft. _____ Linear Ft. _____
Depth of Stone in Lines _____
Water Supply: Individual ( )
Public ( )

Installed by _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: Existing septic tank system - functioning properly at present. If system gives trouble, it must be repaired to the specifications of the Iredell County Health Dept. - House being remodeled

CERTIFICATE OF COMPLETION BY W. M. Howard DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold