IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

REPAIR

OWNER OR CONTRACTOR RICHARD PALO DATE 12/12/90 PERMIT NO. REPAIR

PHONE: Business _____ Home _____

LOCATION US 21 N, TL JABOR RD, TL DUNCAN RD
1ST HOUSE ON (L) S. R. No. _____


SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other REPAIR

No. Bedrooms _____ No. Bathrooms _____
Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )
Lot Area ACRE LOT

Character & Porosity of Soil _____
Percolation Rate _____
Topography EXISTING
Depth to Water Table _____
Rock or other impervious formations _____

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank EXISTING Gals.
Nitrification Field:
No. of Lines 2
Sq. Ft. 480 Linear Ft. 160
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by JAMES HUDDER

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY GLENN FOX, JR

COMMENTS: _____

CERTIFICATE OF COMPLETION BY STEVE HEBERT DATE 12/12/90

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold