J.C. Moore
Certified Operator #985357
Maintenance Report Form

Name and Location of System

Ramon Everardo
168 Ashford Dr,
Olin N.C. 28660

Date of Inspection

4-19-07

Permit Number

136179

County

Iredell

System Classification

IV - A

Name and Address of "ORC"

J.C. Moore
1227 Troutman Drive
Statesville, NC 28625

Phone: (704) 873-2171

Name and Address of Owner

Same

Phone: 704 546 3012

Legend: S-Satisfactory, M-Marginal, U-Unsatisfactory
N-not evaluated, N/A-Nonapplicable

SEPTIC TANK AND PUMP TANK

Date 4-19-07

NO Risers accessible need Riser over outlet lid on
S Signs of Infiltration
S Structurally Sound Septic Tank In order to Clean Filter In Tee
S Landscape Position
NO Filter Cleaned

PUMP

Yes S Pump present and operating
- 72 Design GPM
- 72 Actual GPM
- 100 % Efficiency

S High water alarm operating properly
S Pipework in good condition
S Control panel in good condition
S Control floats operating properly
S Straps and float tree
S Effluent free and clear of solids

LOW PRESSURE PIPE SYSTEM

S Turnups, cleanouts, valves located and protected
S Laterals free of excess solids
~~YES~~ Laterals flushed

Pressure Heads

	Design head	Adjusted head
Line 1	2'	2'
Line 2	2'	2'
Line 3	2'	2'
Line 4		

DRAIN FIELD

S No effluent surfacing
S Surface water diverted
S Line cover maintained properly
S Protected from traffic
S Distribution devices operating properly
S Repair area reserved

COMMENTS

Compliant ✓ Noncompliant ___

Signature J. C. Moore

J.C. Moore
Certified Operator #985357
Maintenance Report Form

Name and Location of System
Ramon Everardo
168 Ashford Dr.
Olin, N.C. 28660

Date of Inspection
10-24-07

Permit Number
136179

County
Iredell

System Classification
IV - A

Name and Address of "ORC"
J.C. Moore
1227 Troutman Drive
Statesville, NC 28625

Name and Address of Owner
Same

Phone (704) 873-2171

Phone 704 546 3012

Legend: S-Satisfactory, M-Marginal, U-Unsatisfactory
N-not evaluated, N/A-Nonapplicable

Date 10-24-07

SEPTIC TANK AND PUMP TANK
NO Risers accessible
S Signs of Infiltration
S Structurally Sound
S Landscape Position
yes Filter Cleaned septic tank has a good amount of solids in outlet compartment

PUMP
yes Pump present and operating
32 Design GPM
35 Actual GPM
109 % Efficiency
yes High water alarm operating properly
S Pipework in good condition
S Control panel in good condition
S Control floats operating properly
S Straps and float tree
S Effluent free and clear of solids

DRAIN FIELD
S No effluent surfacing
S Surface water diverted
S Line cover maintained properly
S Protected from traffic
S Distribution devices operating properly
S Repair area reserved

LOW PRESSURE PIPE SYSTEM
S Turnups, cleanouts, valves located and protected
S Laterals free of excess solids
yes Laterals flushed

Pressure Heads

	Design head	Adjusted head
Line 1	2'	2.2'
Line 2	2'	2.2'
Line 3	2'	2.2'
Line 4		

COMMENTS

Compliant ✓ Noncompliant ___
Signature J.C. Moore

* water from Home Ran into Septic Tank during entire Inspection. recommend to Home owner to check commodes & sinks for leaks & repair them if you find leaks.

* Septic Tank has abnormal amount of solids for age of system. limit or omit Grease from going into System & use Biological Agents to help break down solids

J.C. Moore
Certified Operator #985357
Maintenance Report Form

Name and Location of System

Maria Everarato
168 Ashford Dr
Olin, N.C. 28660

Date of Inspection

4-29-08

Permit Number

136179

County

Iredell

System Classification

IV - A

Name and Address of "ORC"

J.C. Moore
1227 Troutman Drive
Statesville, NC 28625

Phone: (704) 873-2171

Name and Address of Owner

Same

Phone: 704 546 3012

Legend: S-Satisfactory, M-Marginal, U-Unsatisfactory
N-not evaluated, N/A-Nonapplicable

SEPTIC TANK AND PUMP TANK

NO Risers accessible need Riser over Septic Tank
S Signs of Infiltration
S Structurally Sound
S Landscape Position
YES Filter Cleaned

PUMP

YES Pump present and operating
28 Design GPM
30 Actual GPM
107 % Efficiency
YES High water alarm operating properly
S Pipework in good condition
S Control panel in good condition
S Control floats operating properly
S Straps and float tree
S Effluent free and clear of solids

DRAIN FIELD

S No effluent surfacing
S Surface water diverted
S Line cover maintained properly
S Protected from traffic
S Distribution devices operating properly
S Repair area reserved

Date 4-29-08

LOW PRESSURE PIPE SYSTEM

S Turnups, cleanouts, valves located and protected
S Laterals free of excess solids
YES Laterals flushed

Pressure Heads

	Design head	Adjusted head
Line 1	3'	3'
Line 2	3'	3'
Line 3	3'	3'
Line 4		

COMMENTS

Compliant ✓ Noncompliant ___

Signature J. C. Moore

MOORE'S ENVIRONMENTAL SERVICES
1227 TROUTMAN DRIVE
STATESVILLE, NC 28625
HOME: (704) 873-2171
CELL: (704) 902-1122 FAX: (704) 873-9928

Dear maria Everardo:

According to my records, your Type IV-A septic system at 168 Ashford Dr olin N.C. is past due for a renewal on the maintenance contract for the time period of oct 08 to oct 09.

I will need to be contacted by you if you would like to renew your maintenance contract with my company. If I don't hear from you by Nov 15, 2008, I will assume you have made other arrangements and no longer need my services.

According to the North Carolina Department of Environmental Health law #15A.NC, Admin. Code #18A.1961, I am required to notify the Iredell Health Department that I am no longer the operator for your system if you choose not to renew with my company.

Thank you for your past business and hopefully we can continue to do business in the future.

Sincerely,

J. C. moore

J. C. Moore
NC Registered Sanitarian (Cert. #372)
Subsurface System Operator (Cert. #985357)
NC Onsite Wastewater Inspector (Cert. #12331)