IREDELL COUNTY HEALTH DEPARTMENT

IMPROVEMENT PERMIT AND CERTIFICATE OF COMPLETION / OPERATIONS PERMIT

15642

OWNER OR CONTRACTOR AL & CINDY BAXTER DATE 1/8/92 PERMIT NO. 16A-A-45

PHONE: Business _____ Home _____

LOCATION I-77 N, TR NC 901 E, TR TABOR ROAD, TR WILLIAMSBURG ROAD, 3RD BUILT HOUSE ON (R) S.R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House ☑ Mobile Home ☐ Business ☐ Other ADDITION OF ROOM TO HOUSE

No. Bedrooms 3 No. Bathrooms _____

Garbage Disposal Unit Yes ☐ No ☑

Auto. Dishwasher Yes ☑ No ☐

Auto. Wash. Machine Yes ☑ No ☐

Lot Area 3.28 AC

Soil Characteristics _____


Application Rate _____

Topography _____

Depth to Water Table _____

Rock or other impervious formations EXISTING

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement _____ Crawl Space



Plot of System (Not to Scale)

Size of Tank _____ Gals.

Nitrification Field: EXISTING

No. of Lines _____

Sq. Ft. _____ Linear Ft. _____

Depth of Stone in Lines _____

Water Supply: Individual ☐ Public ☑

Installed by _____

I understand and agree to install a septic tank system as specified on this Improvement Permit.

Signed: _____

(IMPROVEMENT PERMIT IS VALID FOR 60 MONTHS FROM DATE OF ISSUE.)

IMPROVEMENT PERMIT BY _____

COMMENTS ① REPAIR AREA IS 100% CONVENTIONAL, GRAVITY-FED.
② KEEP ADDITION MINIMUM 5' FROM SYSTEM.

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY STEVE HEDRICK DATE 1/8/92

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS

Permit is VOID if any unauthorized changes are made in installation of system, and/or if any unapproved changes are made to the site, and/or if any false information is supplied toward securing Improvement Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold