DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: ____
COUNTY: ____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Habitat for Humanity APPLICATION DATE ____
ADDRESS: Hwy 21 N (R) on Tabor Rd, (L) on Spicola DATE EVALUATED: 1/16/01
PROPOSED FACILITY: 3BR 2BA Comm PROPOSED DESIGN FLOW (.1949): ____ PROPERTY SIZE: .66 Ac.
LOCATION OF SITE: ____ PROPERTY RECORDED: Yes
WATER SUPPLY: ☐ Private ☒ Public ☐ Well ☐ Spring ☐ Other ____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	9% Linear	0-6	sc	fr sp SE					PS .35
		6-16	sc	fr sp SE					
		16-48	sc	fr ss sp SE					
2	9% Linear	0-8	sc	fr sp SE					R .35
		8-25	sc	fr sp SE					
		25-48	sc	fr ss sp SE					
3	6% Linear	0-4	sc	fr					PS .3
		4-18	c	vfr					
		18-26	sc	fr					
		26-48	sc	fr					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	Conv, Conv	Conv
Site LTAR	.35	.3

OTHER FACTORS (.1946): ____
SITE CLASSIFICATION (.1948): ____
EVALUATED BY: [signature]
OTHER(S) PRESENT: ____

COMMENTS: ____