ON-SITE WASTEWATER SECTION

COUNTY: IREDELL

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Jimmy Steele APPLICANT: SAME

ADDRESS: P.O. Box 293, HARMONY APPLICATION DATE: 8-29-00 DATE EVALUATED: 9-19-00

PROPOSED FACILITY: 4 BR D/W PROPOSED DESIGN FLOW (.0949): 480 PROPERTY SIZE: 3.51 ACRES

LOCATION OF SITE: SR 77 N, TR NC 901 ~~RD~~ ON LEFT PAST ALLEN RD PROPERTY RECORDED: _____

WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____

EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut

TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFIL CLASS & LTAR
1	SP, ~~SW~~ Ridge Head	0-8	SL	0 gr	N5NP ~~N5NP~~				PS 0.3
		8-36	SCL	fi 2 blk	SSSP SENP				
		36+48	CL	fr 1 blk	SFSP SENP				
2									
3	SL/SLP ~~MOS~~ 5-6	0-15	SL	0 gr	N5NP CENP				PS 0.3
		15-26	SCL	1 blk fr	SFSP CENP				
		26-48	CL	2 blk fi	SFSP CENP				
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	S	PS
System Type(s)	II	II
Site LTAR	0.3	0.3

OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): _____

EVALUATED BY: BILL JOHNSON, SUE HENDRICK

OTHER(S) PRESENT: JIMMY STEELE