IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Donny Allen DATE 14 June 74 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 21 N to Harmony 901 to left. Go appx. 2 mi to R at 1834 on Right. Lot Runs on Right. S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____


House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes ( ) No (✓)
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )

Character & Porosity of Soil Red Clay
Percolation Rate slow
Topography Hill & rock
Depth to Water Table ok
Rock or other impervious formations ok

Lot Area Acreage



Plot of System SL

Size of Tank 1400 Gals.
Nitrification Field: well
No. of Lines 3
Sq. Ft. 675 Linear Ft. 225
Depth of Stone in Lines _____
Water Supply: Individual (✓)
Public ( )

Installed by James Hartness

IMPROVEMENTS PERMIT BY _____

COMMENTS: Pipe downgrade away from septic tank and house.

CERTIFICATE OF COMPLETION BY William M. Howard DATE 14 June 74

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold