IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Mrs Claude Steele DATE 23 July 74 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 21 N to Harmony - 901 left. 1st to Mt. Pleb Church on left. Brick home on right just past entrance to church. S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____


House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 1

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes ( )	No (✓)	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Character & Porosity of Soil Red Clay Loam
Percolation Rate none
Topography Hill Slope
Depth to Water Table ok
Rock or other impervious formations ok

Lot Area average



Size of Tank 1250 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 625 Linear Ft. 250
Depth of Stone in Lines 12" 18"
Water Supply: Individual (✓)
Public ( )

Installed by William Dillard
Mocksville, N.C.

IMPROVEMENTS PERMIT BY William M Howard

COMMENTS: _____

CERTIFICATE OF COMPLETION BY William M Howard DATE 23 July 74

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold