IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Billy Helms DATE 4-7-75 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 21N to Harmony - T.L. on 901 - go to Rd # 1836 on RT - approx .2 mile on left S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____


House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 1

Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes ( ) No (✓)
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )

Lot Area 126 X 126

Character & Porosity of Soil Cecil Clay loam
Percolation Rate 45 mpi
Topography Slight slope to left
Depth to Water Table ok
Rock or other impervious formations ok



Plot of System

Size of Tank 1,000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 625 Linear Ft. 250
Depth of Stone in Lines 10"
Water Supply: Individual (✓)
Public ( )

Installed by Sammy Ramis

IMPROVEMENTS PERMIT BY _____

COMMENTS: Probability of a seasonal high water table

CERTIFICATE OF COMPLETION BY Andrew E. Causey DATE 4-7-75

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold