45401

IREDELL COUNTY HEALTH DEPARTMENT

IMPROVEMENT PERMIT AND CERTIFICATE OF COMPLETION / OPERATIONS PERMIT

14899

OWNER OR CONTRACTOR LARRY R. & PATSY HAYNES DATE 12/8/92 PERMIT NO. 17L-A-20F

PHONE: Business _____ Home _____

LOCATION I-77 N, TR NC 901 E, TL EAGLE MILL ROAD, ~1.0 MILE ON (R) S.R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House ☐ Mobile Home ☑ Business ☐ Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ☐ No ☑

Auto. Dishwasher Yes ☑ No ☐

Auto. Wash. Machine Yes ☑ No ☐

Lot Area 197 x 595'

Soil Characteristics PS

Application Rate 0.35 GPD / FT²

Topography 2-4% LINEAR

Depth to Water Table >4'

Rock or other impervious formations NONE

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement ✓ Crawl Space

ACP 9-14-92

Size of Tank 1000 Gals.

Nitrification Field:


No. of Lines 3

Sq. Ft. 1035 Linear Ft. 345

Depth of Stone in Lines 12"

Water Supply: Individual ☑ WELL

Public ☐



Plot of System (Not to Scale)

Installed by A-1 BACKHOE

I understand and agree to install a septic tank system as specified on this Improvement Permit.

Signed: _____

(IMPROVEMENT PERMIT IS VALID FOR 60 MONTHS FROM DATE OF ISSUE.)

IMPROVEMENT PERMIT BY STEVE HEDRICK

COMMENTS ① REPAIR AREA IS 100% CONVENTIONAL

② KEEP FUTURE SWIMMING POOL MINIMUM 15' FROM SYSTEM

CERTIFICATE OF COMPLETION BY STEVE HEDRICK DATE 12/9/92

EXISTING SYSTEM CHECKED BY _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS

Permit is VOID if any unauthorized changes are made in installation of system, and/or if any unapproved changes are made to the site, and/or if any false information is supplied toward securing Improvement Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold