DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: 4863502713 (AT)
COUNTY: Wake

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: American (LAND) APPLICANT: Clayton Bagwell
ADDRESS: 1281 GARNER BYPASS BLVD, SVL APPLICATION DATE: _____ DATE EVALUATED: 12-8-99
PROPOSED FACILITY: 3BR D/W MH PROPOSED DESIGN FLOW (.1949): 360 PROPERTY SIZE: 1.00 Acre
LOCATION OF SITE: Gulf Shore Ridge III #29 PROPERTY RECORDED: _____
WATER SUPPLY: ☑ Private ☐ ~~Public~~ ☑ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☑ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFIL. CLASS & LTAR
1	SLIGHT N 6%	0-30	SBK / C	FI-SS/SEXP		PS			PS 0.3
		30-42	SBK / CL	FR SEXP					
		42+	ROCK						
2	SLIGHT N 6-8% CUT	0-32	SBK / C	FI-SS/SEXP		PS			PS 0.3
		32-42	SBK / CL	FR / SEXP					
		42+	ROCK						
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	S	S
System Type(s)	II	II
Site LTAR	0.3	0.3

OTHER FACTORS (.1946): None
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: S. IVEY/RICK
OTHER(S) PRESENT: _____