DEPARTMENT OF ENVIRONMENT,
HEALTH & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

DRAFT

SHEET 1 OF 1
PROPERTY I.D.#: 12 N-A-166
DATE: 1-3-96
COUNTY: IREDELL

SOIL SITE EVALUATION FOR ON-SITE WASTEWATER SYSTEM

APPLICANT: LISA WARDO — PHONE: 546-2649
ADDRESS: 2765 HARMONY HWY, HARMONY, NC 28634 — OWNER ___ AGENT: ___
APPLICATION DATE: 12-13-95 — DATE EVALUATED: 1-3-96
PROPOSED FACILITY: 3BR HOUSE W/BASEMENT
PROPERTY SIZE: 4 ACRES
LOCATION OF SITE: US 21 N, TL TOMLIN RD, TL HICKORY GROVE, ON (R) ACROSS FROM BUCKHEAD RD
WATER SUPPLY: On-site Well ___ Comm. Well ___ Public ___ Other ✓ — EVAL. METHOD: Auger Boring ✓ Pit ___ Cut ___

PROFILE #	1940 LANDSCP POS / SLOPE(%)	HORIZON DEPTH (IN.)	.1941 (a)(1) TEXTURE	.1941 (a)(2) STRUCTURE	.1941 (a)(3) MINEROLOGY	MATRIX COLOR	MOTTLE COLOR	OTHER PROFILE FACTORS
1	N	0-48	C	SBK	1:1 / FL			.1942 Wetness Cond. 5
	10%							.1943 Depth/.1956 Sapr. 5
								.1944 Restrictive Hori. 5
								.1948 Profile Class. PS
								Profile LTAR 0.3
2	N	0-48	C	SBK	1:1 / FL			.1942 Wetness Cond. 5
	6%							.1943 Depth/.1956 Sapr. 5
								.1944 Restrictive Hori. 5
								.1948 Profile Class. PS
								Profile LTAR 0.3
3								.1942 Wetness Cond. -
								.1943 Depth/.1956 Sapr. -
								.1944 Restrictive Hori. -
								.1948 Profile Class. -
								Profile LTAR -
4								.1942 Wetness Cond. -
								.1943 Depth/.1956 Sapr. -
								.1944 Restrictive Hori. -
								.1948 Profile Class. -
								Profile LTAR -

AVAILABLE SPACE (.1945): 5 — OTHER FACTORS (.1946): NONE — SOIL CLASSIFICATION (.1948): PS

SYSTEM TYPE: CONV. PUMP-FED — LONG-TERM ACCEPTANCE RATE(S): 0.3

EVALUATED BY: STEVE HEDRICK — OTHER(S) PRESENT: LISA WARDO, DON WARDO

COMMENTS: