IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Blake Millsaps DATE 5-17-89 PERMIT NO. A 8.

PHONE: Business _____ Home _____

LOCATION Hwy 21 N to Harmony - T.L. on Landis Rd. - 4th house on (R) past Deerwood Rd. S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other Repair

No. Bedrooms _____ No. Bathrooms _____


Garbage Disposal Unit	Yes ( )	No ( )
Auto. Dishwasher	Yes ( )	No ( )
Auto. Wash. Machine	Yes ( )	No ( )
Site Suitable	Yes (✓)	No ( )

Lot Area Ample.

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement

Character & Porosity of Soil _____
Percolation Rate Existing.
Topography _____
Depth to Water Table _____
Rock or other impervious formations _____

Size of Tank EXISTING Gals.
Nitrification Field:
No. of Lines 1
Sq. Ft. 300 Lineal Ft. 100
Depth of Stone in Lines 24"
Water Supply: Individual ( )
Public (✓)



Plot of System

Installed by Jerry Revis

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY Ellen Fine Jr.

COMMENTS: Tank pumped & new line installed. New line below existing pit.

CERTIFICATE OF COMPLETION BY Steve Eaton DATE 5-17-89.

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold