IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Edward E. Barkley - present owner Joseph Hamilton - prospective buyer DATE April 18, '78 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 21N to Harmony T.L. on Hwy. 901 T.R. on 1st paved rd to right (Grose St.) next to last House on Rt. S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____


House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms _____ No. Bathrooms _____

Garbage Disposal Unit	Yes ( )	No ( )	
Auto. Dishwasher	Yes ( )	No ( )	
Auto. Wash. Machine	Yes ( )	No ( )	
Site Suitable	Yes ( )	No ( )	

Lot Area _____

Character & Porosity of Soil _____
Percolation Rate _____
Topography _____
Depth to Water Table _____
Rock or other impervious formations _____



Plot of System

Size of Tank existing Gals.
Nitrification Field:
No. of Lines existing
Sq. Ft. _____ Lineal Ft. _____
Depth of Stone in Lines _____
Water Supply: Individual ( )
Public (✓)

Installed by Colon Gallihar

IMPROVEMENTS PERMIT BY _____

COMMENTS: Inspection of existing system revealed no surfacing of sewage at time of inspection. However, sewage system is installed very deep (~2½' deep to septic tank and 6'+ to nitrification field).

CERTIFICATE OF COMPLETION BY Charles R. Hinson DATE April 18, 1978

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold