IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Rama Renegar DATE 03-25-86 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION Harmony - Wht frame house across from N Iredell American Legion Post 113.

SUBDIVISION NAME _____ S. R. No. _____

LOT NO. _____ SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms _____ No. Bathrooms _____

Garbage Disposal Unit Yes ( ) No ( )

Auto. Dishwasher Yes ( ) No ( )

Auto. Wash. Machine Yes ( ) No ( )

Site Suitable Yes ( ) No ( )

Lot Area _____

Repair


Character & Porosity of Soil _____

Percolation Rate _____

Topography existing

Depth to Water Table _____

Rock or other impervious formations _____



Plot of System

Size of Tank Existing Gals.

Nitrification Field:

No. of Lines 1

Sq. Ft. 450 Linear Ft. 150

Depth of Stone in Lines 12"

Water Supply: Individual ( )

Public (✓)

Installed by _____

IMPROVEMENTS PERMIT BY Glenn Fox, JR

COMMENTS: Set tee in tank and new line is feeding first

CERTIFICATE OF COMPLETION BY Jerry L. Price DATE 03-25-86

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold