(Mrs. Mar Harris)

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Jerry Reavis DATE 13 Oct 76 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 21 N. Toward Harmony, Bank house on Right as you enter Harmony across from Benco Service Station S. R. No. _____


SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 1

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	Red Clay
Auto. Dishwasher	Yes ( )	No (✓)	Percolation Rate	none
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	2-6 % Slope
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	ok
			Rock or other impervious formations	ok

Lot Area average



Plot of System

Size of Tank Ryan Gals.

Nitrification Field:
No. of Lines 2
Sq. Ft. 660 Linear Ft. 200
Depth of Stone in Lines 10"

Water Supply: Individual ( )
Public (✓)

Installed by Jerry Reavis

IMPROVEMENTS PERMIT BY _____

COMMENTS: New Tank installed - Lot is good slope

CERTIFICATE OF COMPLETION BY Wm Howard DATE 13 Oct 76

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold