IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Johnny Haynes DATE 4-22-77 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION Harmony – Bldg. on left corner of 901 w. & 21 – S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House ( ) Mobile Home ( ) Business (✓) Other Auto Parts Bldg. + 20 x 40 Rental Space

No. Bedrooms _____ No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No ( )	
Auto. Dishwasher	Yes ( )	No ( )	
Auto. Wash. Machine	Yes ( )	No ( )	
Site Suitable	Yes ( )	No ( )	

Lot Area _____


Character & Porosity of Soil Clay Loam

Percolation Rate mod

Topography 2-6 % Slope

Depth to Water Table 4'

Rock or other impervious formations None



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 6

Sq. Ft. 762 Linear Ft. 280

Depth of Stone in Lines 18"

Water Supply: Individual ( )

Public (✓)

Installed by Harry Rupp

IMPROVEMENTS PERMIT BY W. R. Howard

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Glenn Ford DATE 4/22/77

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold