# IREDELL COUNTY HEALTH DEPARTMENT

## (SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR E. W. Ayers DATE 19 Oct 73 PERMIT NO. _____

PHONE Business _____ Home _____

LOCATION 21 N to Harmony - 901 to Right - Trailer Park Harmony on work S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____


House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 1 No. Bathrooms 1

| | | | |
|---|---|---|---|
| Garbage Disposal Unit | Yes ( ) | No (✓) | |
| Auto. Dishwasher | Yes ( ) | No (✓) | |
| Auto. Wash. Machine | Yes ( ) | No (✓) | |
| Site Suitable | Yes (✓) | No ( ) | |

Character & Porosity of Soil Rocky Clay
Percolation Rate none
Topography Slight Slope
Depth to Water Table none
Rock or other impervious formations Shale

Lot Area _____



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 2
Sq. Ft. 650 Linear Ft. 200
Depth of Stone in Lines _____
Water Supply: Individual ( )
Public ( )

Installed by J. C. Cain

IMPROVEMENTS PERMIT BY _____

COMMENTS: Too much fall on 2½ lots for first 72' - Tile work. System had to be brought up to Iredell County Regulations

CERTIFICATE OF COMPLETION BY William M. Stewart DATE 19 Oct 73

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold