DEPARTMENT OF ENVIRONMENT, HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET ____ OF ____
PROPERTY I.D.#: _____
PROPERTY RECORDED: _____
COUNTY: _____

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: _____ OWNER: __ AGENT: __ PHONE: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: _____
_____ PROPOSED FACILITY: _____
_____ PROPERTY SIZE: _____
LOCATION OF SITE: Sauer Field
WATER SUPPLY: On-Site Well____ Comm. Well___ Public____ Other_____ EVAL. METHOD: Auger Boring___ Pit___ Cut___

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
1	(3)	0-8	RC WSBK	FRI SP					(4)
		8-22	Cl WFSBK	FRI SP					
		22+	Cl Saprolite Material	FRS SP					
2	(4)	0-8	Cl WSBK	FRI SS,SP		Rock / weathered rock			(4)
		8-19	Cl Saprolite material	SS SP					
		19+	Rock / Saprolite / weathered rock						
3	(5)	0-8	Cl WSBK	FRI SS,SP					
		8-36	RC SBK	FI S,P					
		36-48	Cl WSBK	FRI SS,SP					
~~37~~ 4	(1)	0-8	Scl WSBK	FRI SS SP					PS
		8-36	RC SBK	FI S,P					
		36-48	Cl WSBK	FRI SS,SP					
	Shallow								
5	(2)	0-7	HCl WSBK	FRI SS,SP					PS
		7-20	RC SBK	FI S,P					
		20-27	Cl WFSBK	FRI SS,P	- Inclusions of Saprolite				10
		27-36	l Saprolite GR	FRI SS,NP					20 -
		36-48	l Saprolite GR	VFRI SS,PO	~ Slt				

AVAILABLE SPACE (.1945)_____ SITE CLASSIFICATION (.1948): _____ SITE LONG-TERM ACCEPTANCE RATE: _____
EVALUATED BY: _____ OTHER(S) PRESENT: _____
COMMENTS: _____