IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Columbus Campbell DATE June 22, 1977 PERMIT NO. _____

PHONE Business _____ Home _____

LOCATION Hwy 21 N to Harmony, T.R. on Hwy 901, go to Church St. on left go to Trailer on left near end of Street S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 1½

Garbage Disposal Unit Yes ( ) No (✓)

Solid Waste Yes ( ) No (✓)

Solid Waste Yes (✓) No ( )

Site Suitable Yes (✓) No ( )

Character & Porosity of Soil Cecil Clay


Percolation Rate Average

Topography Gently Slope

Depth to Water Table 60"

Rock or other impervious formations None

Type Area Average



Plot of System

Size of Tank 1000 Gals

Nitrification Field

No. of Lines 2

Sq. Ft. 625 Linear Ft. 250

Depth of Stone in Lines 10"

Water Supply Individual ( )
Public (✓)

Installed by Bobby Combs

IMPROVEMENTS PERMIT BY _____

COMMENTS _____

CERTIFICATE OF COMPLETION BY Andrew C Carey DATE 6-28-77

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS

Health Dept. Copy White Inspection Dept. Copy Yellow Sanitarian's Copy Pink Owner's Copy Gold