SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Harmony Properties OWNER: AGENT: PHONE:
ADDRESS: APPLICATION DATE: DATE EVALUATED:
PROPOSED FACILITY:
PROPERTY SIZE:
LOCATION OF SITE: Sage Field lot 46
WATER SUPPLY: On-Site Well Comm. Well Public Other EVAL. METHOD: Auger Boring ✓ Pit Cu

PROFILE #	1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	1941 STRUCTURE/TEXTURE	1941 MINERALOGY/ CONSISTENCE	1942 WETNESS COND.	1944 RESTRICT HORIZONS	1948 CLASS OF HORIZ	1937/ 1956 SAPRLT CLASS.	HORIZ LTA
Hole	NOSL 10%	0to48	C SbK	SEAP Sticky Firm clay	PS	PS	PS	N/A	.25
Hole 2	NOSL 12%	0to48	C SbK	SEAP sticky Firm	PS	PS	PS	N/A	.25
Pit 3	NONE 10%	0to48	C SiK	SEAP Firm clay sticky Plastic	PS	PS	PS	N/A	.25
Pit 4	NONE 10%	0to48	C SbK	SEAP Firm clay	PS	PS	PS	N/A	.25
5									

SUITABLE SPACE (1945): Yes SITE CLASSIFICATION (1948): PS SITE LONG-TERM ACCEPTANCE RATE: .25
EVALUATED BY: G.C. Moore OTHER(S) PRESENT: Jim Barkley
COMMENTS:

000975