SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Harmony Properties OWNER: AGENT: PHONE:
ADDRESS: APPLICATION DATE: DATE EVALUATED:
PROPOSED FACILITY:
PROPERTY SIZE:
LOCATION OF SITE:
WATER SUPPLY: On-Site Well Comm. Well Public Other EVAL. METHOD: Auger Boring Pit Cu

PROFILE #	.1940 LANDSCP POS. (G)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZ LTA
1	8% Linear	0 to 45	C	SBK SEAP SS SP	PS	PS	PS	N/A	.13
2	8% Linear + Nose	0 to 24	C	SBK SEAP SS SP	PS	PS	PS	N/A	.33
		24 to 44/CL	WSBK	SEAP					
3									
4									
5									

AVAILABLE SPACE (.1945): Yes SITE CLASSIFICATION (1949): PS SITE LONG-TERM ACCEPTANCE RATE: .13
EVALUATED BY: [illegible] OTHER(S) PRESENT: Tim Barkley
COMMENTS: