IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Harmony Milling Co. DATE 9-23-77 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 21 N T.L. on 901 Go ~ 1 mi. House on left

_____ S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 1½

Character & Porosity of Soil Cecil loam

Garbage Disposal Unit Yes ( ) No (✓)

Percolation Rate _____

Auto. Dishwasher Yes ( ) No (✓)

Topography 4 to 6%


Auto. Wash. Machine Yes (✓) No ( )

Depth to Water Table sunk.

Site Suitable Yes (✓) No ( )

Rock or other impervious formations none obs.

Lot Area 22,500 ft²



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 2

Sq. Ft. 625 Linear Ft. 250

Depth of Stone in Lines 10"

Water Supply: Individual ( )

Public (✓)

Installed by Junior Abson

IMPROVEMENTS PERMIT BY W. M. Howard

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Wm. B. Stevens DATE 9-23-77

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold