IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Edward E. Barkley DATE April 24, '78 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 21 N T.L. on 901 - 1 mile W. of Harmony on Rt. _____ S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____


House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 1 3/4

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Lot Area acreage

Character & Porosity of Soil Cecil clay loam
Percolation Rate _____
Topography 4-6%
Depth to Water Table wnl.
Rock or other impervious formations none obs.



Plot of System

Size of Tank 1500 Gals.
Nitrification Field:
No. of Lines 2
Sq. Ft. 750 Linear Ft. 250
Depth of Stone in Lines 10" +
Water Supply: Individual ( )
Public (✓)

Installed by Sammy Lewis

IMPROVEMENTS PERMIT BY A.R. Hinson

COMMENTS: _____

CERTIFICATE OF COMPLETION BY David R Hinson DATE Jan 24, '78

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold