04459

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Edward Carter DATE 4-21-86 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION Harmony 21 N. TR on Hayes St.

_____ S. R. No. _____


SUBDIVISION NAME _____ LOT NO. 12 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 2	No. Bathrooms 2		Character & Porosity of Soil	Loam-Sandy Clay
Garbage Disposal Unit	Yes ( )	No (✓)	Percolation Rate	5 Days at 1 gal
Auto. Dishwasher	Yes (✓)	No ( )	Topography	5 - 6%
Auto. Wash. Machine	Yes (✓)	No ( )	Depth to Water Table	10'
Site Suitable	Yes (✓)	No ( )	Rock or other impervious formations	None

Lot Area 95/185

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 2

Sq. Ft. 720 Linear Ft. 240

Depth of Stone in Lines 12"

Water Supply: Individual ( )

Public (✓)

Installed by Paul Trucking Co.

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: _____

CERTIFICATE OF COMPLETION BY _____ DATE 4/21/86

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold