IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System — G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR George Myers DATE 11/5/75 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION Hwy 21N thru Harmony to Rt# 1839 on left, 1st house on left

S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 1

Garbage Disposal Unit Yes ( ) No (✓)

Auto. Dishwasher Yes ( ) No (✓)

Auto. Wash. Machine Yes (✓) No ( )

Site Suitable Yes (✓) No ( )

Lot Area 1 acre

Character & Porosity of Soil Cecil Clay

Percolation Rate none

Topography slope to east

Depth to Water Table unknown

Rock or other impervious formations unknown

Repair

Size of Tank sixty Gals.

Nitrification Field:


No. of Lines 2

Sq. Ft. 625 Linear Ft. 250

Depth of Stone in Lines 10"

Water Supply: Individual (✓)

Public ( )



Plot of System

Installed by Roy Lentz

IMPROVEMENTS PERMIT BY _____

COMMENTS: Suggested that tank should be checked for pumping if necessary.

CERTIFICATE OF COMPLETION BY Andrew E. Camp DATE 11/5/75

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold