DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of _
PROPERTY ID #: _____
COUNTY: PENDER

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: North 21 LLC APPLICANT: SAME
ADDRESS: 3533 Dawson R, CHAR, 28215 APPLICATION DATE: 3-7-02 DATE EVALUATED: 3-21-02
PROPOSED FACILITY: 3BR D/W MH PROPOSED DESIGN FLOW (.1949): 360 PROPERTY SIZE: 0.698 ACRE
LOCATION OF SITE: GRANTS GLEN LOT #1 PROPERTY RECORDED: _____
WATER SUPPLY: ☑ Private ☐ Public ☑ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFIL CLASS & LTAR
1	L 12%	0-20	SBK C	FI ~~SEXP~~					PS 0.4
		20-48	SBK MICACEOUS SC	FR ~~SEXP~~					
2	SLIGHT N 10%	0-29	SBK SC	FR SEXP					PS 0.4
		29-48	SAPROLITE SL	VFR SEXP					
3	L 8%	0-18	SBK C	FR SEXP					PS 0.4
		18-48	SBK SC	VFR SEXP					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	S	S
System Type(s)	II	III IV
Site LTAR	0.4	0.4

OTHER FACTORS (.1946): NONE
SITE CLASSIFICATION (.1948): PF
EVALUATED BY: S. HEDRICK
OTHER(S) PRESENT: BOB & RICK HILL