DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: North 21 LLC
APPLICANT: Fleetwood Homes of Statesville
ADDRESS: _____
APPLICATION DATE: _____
DATE EVALUATED: 7/15
PROPOSED FACILITY: 3BR mH
PROPOSED DESIGN FLOW (.1949): 360
PROPERTY SIZE: Yes
LOCATION OF SITE: _____
PROPERTY RECORDED: _____
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed
Lot #4 Grove Glenn

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFIL CLASS & LTAR
1	Linear 16%	0-27	c ABk	FR SS/SP SEAP					PS .40
		27-48	S.sprnty c Bk	VFR SEAP					
			clmx						
2	Linear 9%	0-24	c Abk	fr SS/SP SEAP					PS .40
		24-48	wBk S.sprnty clmx	VFR SEAP					
3	Linear 16%	0-26	c/cc SBk	fr SS/SP SEAP					PS .40
		26-48	S.sprnty clmx	wBk VFR SEAP					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	Trench Conventional	Pump/25%
Site LTAR	.40	.40

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: Billy Cohn
OTHER(S) PRESENT: _____