Previously owned by J.C. Griffin

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Andy J. Blevins DATE 28 Feb 74 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 21 N to Harmony - 901 & Right & My View Lake on Left Lot # 3 on Right side of Lake. S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____ Existing System

No. Bedrooms 3 No. Bathrooms 1½

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes ( )	No (✓)	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Lot Area 20,000 plus


Character & Porosity of Soil Clay Loam

Percolation Rate none

Topography Slope & Fair

Depth to Water Table unk

Rock or other impervious formations unk (well)



Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 2

Sq. Ft. _____ Linear Ft. 225

Depth of Stone in Lines _____

Water Supply: Individual (✓)

Public ( )

Installed by _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: Syste installed in 1973. Syste functioning properly

CERTIFICATE OF COMPLETION BY William M Howard DATE 28 Feb 74

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold