IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System — G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Ralph Chambers DATE 10 Mar 77 PERMIT NO. _____

PHONE: Business _____ Home _____


LOCATION Hwy 21 N To Harmony - T.R. on 901. Go to Sky View Lake on left. Bear right at entrance - 3rd trailer on right. S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other Double wide

No. Bedrooms 3 No. Bathrooms 1½

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	Red Clay	
Auto. Dishwasher	Yes ( )	No (✓)	Percolation Rate	none	
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	2-6% slope	
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	∞	
Lot Area _____			Rock or other impervious formations	∞	



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 2
Sq. Ft. 562½ Linear Ft. 225
Depth of Stone in Lines 10"

Water Supply: Individual (✓)
Public ( )

Installed by Davis Septic Tank Co.

IMPROVEMENTS PERMIT BY _____

COMMENTS: Syster installed in 1973 - Syster functioning properly & pumped.

CERTIFICATE OF COMPLETION BY W. M. Linnell DATE 10 Mar 77

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold