DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: IREDELL

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

4880-94-1957

OWNER: RALPH (GLEN) CAMPBELL APPLICANT: DAVE
ADDRESS: 711 E. MEMORIAL HWY, STATESVILLE APPLICATION DATE: 8 6 02 DATE EVALUATED: 8.21.02
PROPOSED FACILITY: 3BR S/LI PROPOSED DESIGN FLOW (.1949): 360 PROPERTY SIZE: 3.62 ACRES
LOCATION OF SITE: US 21 N, TR NC 901, TL SHEFFIELD, ON LEFT PAST DYKE PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☒ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFIL CLASS & LTAR
1	N 10%	0-23	SBK CL	FR SEP					PS 0.4
		23-37	WSBK SCL	VFR SEP					
		37+	WEATHERED ROCK						
2	N 17%	0-28	SBK CL	FR SEP					PS 0.4
		28-38	WSBK SCL	VFR SEP					
		38-48	WEATHERED ROCK						
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	S	S
System Type(s)	I	II
Site LTAR	0.4	0.4

OTHER FACTORS (.1946): NONE
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: S. HENDRICK
OTHER(S) PRESENT: GLEN CAMPBELL